PAGE: 1 PRINT DATE: 06/08/90

S050250L ATTACHMENT -Page 46 of 152

FAILURE MODES EFFECTS AMALYSIS (FMEA) -- CRITICAL HARDWARE

NUMBER: MO-AA2-110-X

SUBSYSTEM NAME: STABILIZED PAYLOAD DEPLOYMENT SYSTEM

REVISION: 2 06/08/90

PART NAME VENDOR NAME PART NUMBER VENDOR NUMBER

m ASSEM :

PANEL A6A1

V070-730325

■ SRU :

SWITCH. ROTARY

ME452-0093-5031

PART DATA

- EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
- RÉFERENCE DESIGNATORS: 36V73A6A1 \$37
- QUANTITY OF LIKE ITEMS: 1
- FUNCTION:
 SWITCH \$37 IS A MULTIPOLE ROTAPY SWITCH THAT PROVIDES ALTERNATE
 CAPABILITY TO SELECTIVELY SUPPLY MAIN DCA AND MAIN DCB TO SPECIFIC
 LOGIC CONTROL CIRCUITS FOR THE STABILIZED PAYLOAD DEPLOYMENT SYSTEM
 OPERATION. DEPENDENT ON THE SWITCH POSITION, MAIN DC A, MAIN DC B
 AND OPERATIONAL INSTRUMENTATION AND TALKBACKS WILL BE CONDUCTED THROUGH
 THE SWITCH.

CRITICALITY OF THIS FAILURE MODE: ALURE MO	
CRITICALITY OF THIS FAILURE MODE: FAILURE MO	
CRITICALITY OF THIS FAILURE MODE: FAILURE MO	
CRITICALITY OF THIS FAILURE MODE: FAILURE MO	
CRITICALITY OF THIS FAILURE MODE: FAILS OPEN (ALL CONTACTS) RISSION PHASE: O ON-ORBIT PEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA 2 103 BISCOVERY 3 104 ATLANTIS 2 105 ENDEAVOUR CAUSE: PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL HOCK, PROCESSING ANOMALY RITICALITY I/I DURING INTACT ABORT ONLY? NO EDUNDANCY SCREEN A) PASS B) PASS	
CRITICALITY OF THIS FAILURE MODE: FAILURE MO	
CRITICALITY OF THIS FAILURE MODE: FAILURE MO	
CRITICALITY OF THIS FAILURE MODE: FAILURE MO	
CRITICALITY OF THIS FAILURE MODE: 1R2 FAILURE MODE: FAILU	
CRITICALITY OF THIS FAILURE MODE: 1R2 FAILURE MODE: FAILURE MODE: FAILURE MODE:	
CRITICALITY OF THIS THEM NAME: SWITCH, ROTARY FAILURE MODE:1R2 FAILURE MODE:	
CRITICALITY OF THIS TEM NAME: SWITCH, ROTARY FAILURE MODE:1R2	
·- · · ·	
MLMBER: MO-AA2-110-02 REVISION/ 2 06/08/90	

PAGE: 6

PRINT DATE: 06/08/90 8050250L

S050250L ATTACHMENT -Page 48 of 152

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: MO-AA2-110-02

- (B) INTERFACING SUBSYSTEM(S):
 LOSS OF YO, PRIMARY AND SECONDARY RDU CONTROL REDUNDANCY,
 LOSS OF OPERATIONAL INSTRUMENTATION, AND TALKBACK.
- (C) MISSION:
 FIRST FAILURE LOSS OF MISSION. LOSS OF ALL ALTERNATE SELECT
 CAPABILITY TO CONTROL YO AND RDU DRIVE ACTUATOR.
- (D) CREW. VEHICLE, AND ELEMENT(S):
 POSSIBLE LOSS OF CREW/VEHICLE WITH PARTIAL PAYLOAD DEPLOYMENT PREVENTING
 PAYLOAD BAY DOOR CLOSURE.
- (E) FUNCTIONAL CRITICALITY EFFECTS:
 LOSS OF ALL CAPABILITY TO SELECT YO AND ROU DRIVE FUNCTION. COMBINED
 FAILURES COULD RESULT IN PARTIAL PAYLOAD DEPLOYMENT PREVENTING PAYLOAD
 BAYDOOR CLOSURE. RESULTING IN POSSIBLE LOSS OF CREW AND VEHICLE.

- DISPOSITION RATIONALE -

- (A) DESIGN: REFER TO APPENDIX A, ITEM 2.
- (B) TEST: REFER TO APPENDIX A, ITEM 2.

OMRSD: GROUND TURNAROUND FREQUENCY OF CHECKOUT IS MISSION DEPENDENT. DUAL MOTOR FUNCTIONAL, VERIFIES SWITCH OPERATION \$0790A.020-B.

- (C) INSPECTION: REFER TO APPENDIX A, ITEM 2.
- (0) FAILURE HISTORY: REFER TO APPENDIX A, ITEM 2.
- (E) OPERATIONAL USE: NOME.

PAGE:

PRINT DATE: 06/08/90

\$050250L ATTACHMENT -Page 49 of 152

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE

NUMBER: MO-AA2-110-02

APPROVALS -

RELIABILITY ENGINEERING: W. R. MARLOWE DESIGN ENGINEERING : T. TAUFER

DESIGN ENGINEERING

QUALITY ENGINEERING

NASA RELIABILITY

NASA SUBSYSTEM MANAGER : MASA EPO&C RELIABILITY :

MASA QUALITY ASSURANCE : NASA EPO&C SUBSYS MGR :

: T. TAUFER

: M. F. MERGEN

[WOODARD 7/19/90

MO-AA - 49